

30 December 1975

MEMORANDUM FOR THE RECORD

UBJECT: Meeting with AMPEX on 18 December 1975

1. The following people were present at the meeting:

AMPEX

AGENCY

Milan Telian Fred Wydler Fracy Wood William Slingland Diane Lemos

н.	Fitzwater,	

2. Mr. Telian opened the meeting, he said AMPEX would present a detailed analysis of the Redwood City PSAT and then address the other items listed in the 4 December letter from to the AMPEX Corporation. Reproductions of all slides used by AMPEX during the meeting are attached to this report.

STAT

3. Mr. Slingland presented a series of slides and much commentary that summarized the AMPEX view of the results of the Redwood City PSAT. He stressed that AMPEX believed that PSAT was a "joint discovery" exercise which would present the system "as it was" and see where we are and what it will take to go on. He went on to say that the PSAT required "perfect" tardware, that the tests had extensive interdependencies, and that there were functions tested that were not included in telease 1. Mr. \_\_\_\_\_ asked when this condition had been discovered, the answer was in October. (The tests were delivered in August, I revised set was delivered in October.)

STAT

STAT

4. Mr. Slingland made a strong point that the hardware rrors were much reduced on the fifth day of the PSAT. This improvement was because of an adjustment that was made to the ata Channel and due to the installation of a software feature hat causes data to be read immediately after it has been ritten to tape. This was the start of their tactic to show in ability to resolve problems quickly rather than explain why hey were so unprepared for PSAT. The rest of Mr. Slingland's resentation summarized the number and types of failures experienced the Redwood City PSAT. The AMPEX summary showed a total of

sixty-four failures, forty-six were hardware related and eighteen were software related. Mr. Slingland claimed that eleven of the software failures were fixed either during or immediately after PSAT and that six were related to recovery functions and thus should not have been tested at the PSAT.

- STAT 5. Messrs \_\_\_\_\_\_ disagreed with AMPEX interpretation of recovery functions, a separate report on this problem is being prepared. The points that were contended are listed below:
  - a. Data that cannot be moved from disk to tape by the Mass Storage System but which can be successfully read by problem programs executing in a host computer.
  - b. Data files that have records that overflow a disk cylinder boundary.
  - c. Reserve of a shared disk unit.
  - d. Allocation lockout, space deallocated on disk without MSS notification, wait loop for space.
  - e. Display file abort-allocation lockout.
  - f. Software time out to TDP after last interrupt.
  - g. Incorrect MFD entries due to manual restart procedures.
  - h. MSS sent incorrect message to host then hung looping.
  - i. Automatic demark.
  - 6. Mr. Slingland presented a slide that summarized the forty-six hardware failures. Twenty-six failures were associated with moving data from disk to tape, twenty of these occurred in the first four days before AMPEX fixed the hardware and software, the remaining six failures were claimed to be related to recovery and thus not appropriate for the PSAT. Ten failures were associated with moving data from disk to tape, these all occurred within the first four days and an implication was left that this problem is now permanently cured. Two failures were caused by a communication interface unit between the SCP and EDCP and eight failures were caused by a faulty interrupt handling design which AMPEX says is now fixed.
- STAT 7. \_\_\_\_\_\_ noted that the large number of hardware errors had prevented the Agency from running all of the tests of the Release 1 software functions. Just over half of the software functions planned to be tested were actually tested at the PSAT. Mr. Slingland said that the Redwood City hardware consists of prototype units and is not the equipment that will be delivered to the Agency. No mention was made of the extensive effort AMPEX allocates to this equipment, it is also important to note that the AMPEX programmers say the Redwood City hardware performs better than that at Sunnyvale.

Ball Lat. Will Control

- 8. Mr. Wood presented a detailed discussion of the hardware problems encountered at PSAT. He reviewed four slides that broke out the types of failures, in what test session the failures occurred, the corrective actions taken by AMPEX, and the reason if none were taken which invariably was because the failure was recovery related and should not have been tested at PSAT. The Agency's position is that the failures noted by AMPEX are not recovery related but rather normal error handling that should already be completed.
- 9. When Mr. Wood was questioned about some of the hardware failures, he admitted that the tape used in the test had bad spots and also had not been completely pre-tested as had been requested. He said that the function of detecting bad areas on tape during a normal write process was not a PSAT function. October reporting by AMPEX described this function's status as completed. July reporting also stated it as complete and that it was planned to be tested at PSAT. It seems to me that the problem here is that the tally track hardware is not finished and AMPEX does not want to make this admission. Further discussion of the hardware problems resulted in both Messrs Wood and Telian admitting that AMPEX was unprepared for PSAT.
- 10. Mr. Wood described the hardware failures caused by the communications interface between the SCP and EDCP, the Channel Simulator, and a missing wire in the Transport Driver Interface Unit.

  | asked if AMPEX had diagnostics to find missing wires. AMPEX did not directly answer the question. then continued and said the Agency is concerned about hardware reliability.

- 11. The last part of Mr. Wood's presentation was a discussion of error rates. He stated that the unrecoverable or hard error rate is 1 byte for each 2.5 billion bytes read (transferred from tape to disk). He said that based on the daily volume of data stated in the Mass Storage System Design that we should expect approximately two such errors per day. He also said that there was not a high enough volume of data to make any meaningful statistical evaluation of the error rate observed during the Redwood City PSAT. Finally, he noted that of all data successfully read during PSAT, there were no data compare failures. The fact remains that eleven out of seventy files were lost during PSAT because of various errors.
- 12. The points made by Mr. Wood during his presentation were the same as those made by Mr. Slingland. Yes there were failures, in this case hardware, but they had been corrected

either during PSAT or immediately after and those that were not corrected are related to recovery functions which are not a part of PSAT. The Agency does not agree with Mr. Wood's interpretation of the recovery functions.

- an analysis of the PSAT software failures. She reviewed a selected set of errors and claimed they had been corrected either during or immediately after the PSAT. The remainder were all categorized as related to recovery functions which were not to be tested at the Redwood City PSAT. Messrs disagreed with Ampex's interpretation that these failures were related to the recovery functions as specified in section 6 of the MSS Design document.
- and admitted that the PSAT had not satisfied the contractual milestone. However, he continued that in Ampex's view they had demonstrated a basic capability of the MSS hardware and software to do the functions specified. He went on to say that there was a misunderstanding about the content of PSAT and no agreement as to its content. This situation had led to AMPEX and the Agency viewing the results differently. He then proposed a technical meeting in early January for the purpose of reaching agreement and for scheduling another PSAT. Mr. said that before the Government agrees to anything, we would like to hear the rest of Ampex's presentation.
- 15. Ampex then went on to address the four design items that the Government had stated appeared to be contrary to the system specifications. Mr. Slingland presented the Ampex position on each item with the aid of four slides.

Item 1 was entitled, "Concurrent access to individual transport drivers from both storage control processors". Ampex said that this type of access was not required by the contract or specification. To support this stand a cabling diagram in the MSS Design was referenced and also a section on Oracle Maintenance and Diagnostics. Mr. \_\_\_\_\_\_ argued that the MSS Design specifically states that an SCP and a transport driver must be capable of operating in off-line mode, and the only way this capability is possible is for Ampex to supply concurrent accessing. Mr. Wood appeared to agree that the Government's arguement was irrefutable. Mr. \_\_\_\_\_\_ pointed out our desire

STAT

**STAT** 

STAT

STAT

### State of the state Approved For Release 2004/10/28 : CIA-RDP80-01794R000100230003-3

The Parlichment where to the analysis and the second second

o be able to split the system for maintenance, development nd debugging which would be impossible without this feature.

Item 2 was entitled, "Maximum hardware configration of 6 TD's, 64 Tape Transporter, 3 DC's, and 6 EDCP's oes not have "perfect switching" capability." Ampex said hey would provide a "perfect switching" capability when the gency orders a maximum configuration. Mr. \_\_\_\_\_ argued that he MSS General System Specification called for perfect witching for all hardware configurations that did not exceed standard configuration of 6 TD's, 64 Transports, 3 DC's, and EDCP's. Ampex claimed that the MSS Design document negated he General System Specification, the Government disagreed with pointed out that the his contention. Messrs \_\_\_\_\_ and \_\_\_ ISS Design document is primarily a software specification and hat the hardware specifications which exist in other documents ere not meant to be repeated in the MSS Design.

Item 3 was entitled, "A storage control processor equires a dedicated disk controller to access the MSS private 'iles". The Ampex position on this item was that the MSS can perate with a shared BSS/MSS controller, however, they recommend that a dedicated controller be used for performance reasons. the Government stated that the system design specifies conrollers are shared for access to the BSS and to the private

Item 4 was entitled, "Functions are not split and/ or shared between the two (2) storage control processors". impex addressed this item by trying to justify their design witch to a single SCP mode. They admitted erring in not idvising the Government sooner. In spite of this admission, ir. Slingland then said the SCP software function split is not lescribed in the contract. \_\_\_\_\_\_ refuted this by citing everal references where the master-slave split is described .n much detail. The slide accompanying item 4 also states that :he Ampex "cost-to-complete" estimate used to negotiate the eiling price assumed a single SCP approach. If this is :rue, why wasn't the specification changed at the same time.

Mr. Wydler, continued to justify Ampex position for leveloping a single SCP system. He said that all of the 1975 25X hare development was based on this concept. He gave several 25X hard arguments for the concept; higher reliability, MTTR improved, SCP failure no degradation and more (see the slide). noted that none of these arguments were advantageous ir. and are minded Mr. Wodler that Ampex justified developing CPOS on the basis of a dual SCP system. Mr. Wydler and obviously exhausted his knowledge of the subject and did not respond. Lastly, Mr. Wydler said that the single SCP system STAT

STAT

STAT

111 be supported for the general market, leaving the implication that a dual system as called for by the specification ould make that system a one-of-a-kind product.

17. After Mr. Wydler's presentation, Mr. then
sked Ampex about their schedule projections. Mr. Telian
aid that schedules will have to be ignored until the Redwood
Ity and Sunnyvale PSAT's have been agreed upon. Mr.
nen asked when will you deliver the system assuming the system
esign Ampex argued for. Mr. Telian said Ampex cannot discuss
chedules with meaningful significance until they satisfy PSAT.
again asked when can we expect delivery. Mr. Telian
esponded with a no comment and then continued that without
orther discussion about the issues that we are divided on,
spex cannot tell us anything about going on with the project.
spex then requested time for a caucus which lasted an hour.

- 18. Mr. Telian presented the Ampex position. He said nat Ampex intends to live up to and abide by the contract. Impex realizes that it is important to deliver a useable system of only for the Agency but it is important for market considerations as well. He went on to say it is obvious that more esearch must be done to clarify the positions raised in the seting. He emphasized that the first six months of 1975 were pent on design and only two days were spent to research the exceptions list in amendment five. Their haste in doing that ay have caused Ampex to miss some things that got into the enegotiated amendment. Until that research is done, Ampex annot say anything about schedules. (My comment is that f Ampex had really spent 6 months on design there would not be any problems today.)
- 19. After making the above statements, Mr. Telian then isplayed a slide entitled, "TMS-2 Delivery Schedule", which ontained several vague generalities. However, in his discussion, r. Telian said that the Sunnyvale PSAT would be complete in may 1976, the hardware would be shipped in July 1976, and final acceptance testing would start on November 30, 1976.

The contractual date for starting final acceptance s May 1976, thus the November date represents a slip of six onths. The schedule was made just six months ago in June 1975. The November date also represents the Ampex interpretation of the stem which is less than that described in the contracts.

STAT

STAT

STAT

まるとうしてくくしょ みこうてきないないないないないないないできないないしていましているというないないからい

STAT 20. Mr. asked Mr. Telian to assess the impact on the schedule if Ampex complies with the Government's view of the four disputed areas. Mr. Telian said he could not answer until early January.

21. The meeting adjourned.

COTR, Project ORACLE

STAT

# TMS-2 MASS STORAGE SYSTEM

# REDWOOD CITY PSAT BACKGROUND

"JOINT DISCOVERY" APPROACH BELIEVED BENEFICIAL IN UNDER-STANDING OVERALL SOFTWARE DEVELOPMENT PROGRESS.

- As a result, Ampex modified own preparation ground rules to meet November 19 schedule.
- EXTENSIVE TEST DEPENDENCY REQUIRED "PERFECT" HARDWARE

  OPERATION OR "RECOVERY/WARM START" CAPABILITIES NOT ANTI
  CIPATED IN Release 1.
- INORDINATE NUMBER OF ASCEND/DESCEND FAILURES OCCURRED FIRST FOUR(4) DAYS OF TESTING.
- DRAMATIC IMPROVEMENT IN SYSTEM RELIABILITY AFTER INSTALLATION OF READ-VERIFY AND DATA CHANNEL ADJUSTMENT.

# Appitological for Release 2004/16/28 CTAIRDP80-01794R000100230003-3 REDWOOD CITY PSAT SUMMARY

TWENTY(20) TEST SESSIONS DURING SEVEN(7) DAY PERIOD, NOVEMBER 19-25, 1975.

APPROXIMATELY THIRTY-ONE (31) Hours OF TESTING, INCLUDING Eight (8) Hours Stand Alone.

## DESCEND DATA - DISK TO TAPE

TOTAL ATTEMPTS	231
Successful .	205
FAILED BEFORE CORRECTIVE ACTION	20
FAILED AFTER CORRECTIVE ACTION	6
(ALL RECOVERY RELATED)	٠

# ASCEND DATA - TAPE TO DISK

TOTAL ATTEMPTS	126
Successful	116
FAILED BEFORE CORRECTIVE ACTION	10
FAILED AFTER CORRECTIVE ACTION	0

CONCLUSION - NO FILES LOST AFTER CORRECTIVE ACTION IMPLEMENTED.

# TMS-2 MASS STORAGE SYSTEM RWC PSAT OVERVIEW FAILURE - CORRECTIVE ACTION SUMMARY

SIXTY-FOUR (64) OCCURRENCES IDENTIFIED

FORTY-SIX(46) - HARDWARE RELATED

EIGHTEEN(18) - SOFTWARE RELATED

#### ALL PROBLEMS DIAGNOSED AND,

- 1. Fixes implemented for all Release 1 features except set segment size < 10 scheduled for Final.
- 2. Remaining items all related to recovery and scheduled for Final Release.

# RWC PSAT SUMMARY HARDWARE RELATED FAILURES - 46

Twenty-six(26) Occurrences

Descending Data from Disk to Tape

- Twenty(20) PRIOR TO INSTALLATION OF FIXES.
- Six(6) AFTER "Read Verify" Software and Data Channel Adjustment. All related to Recovery not supported by Release 1.

Ten(10) Occurrences

Ascending Data from Tape to Disk

- None After FIXES INSTALLED.

Two(2) Occurrences

DA-11 DEC Interface Between SCP & EDCP

- REPLACED HARDWARE.
- RANDOM FAILURE.

EIGHT(8) OCCURRENCES

CHANNEL SIMULATOR/TRANSPORT DRIVER INTERRUPT HANDLING DESIGN Error caused Hard System Aborts

- Corrective action implemented.

# ApprovedS-02 Release 2000A710628 :SYIA-FEDP80-01794R000100230003-3 RWC PSAT SUIMARY SOFTWARE RELATED FAILURES - 18

- o Twelve(12) Occurrences

  Functional Deficiencies In Release 1 Software
  - ELEVEN(11) CORRECTIVE ACTION IMPLEMENTED, INSTALLED, AND TESTED OK.
  - ONE(1) (SET SEGMENT TIME LIMIT 10) PARTIAL CAPABILITY
    IN PLACE BALANCE FOR FINAL RELEASE.
  - o Six(6) Occurrences

FINAL RELEASE RECOVERY IMPLICATIONS.

#### SUMMARY OF PSAT HARDWARE EVENTS

	Occurrence
Descend Failures	26
Ascend Failures	10
DAll Between SCP & EDCP	2
SAll & TDIF Interrupt Processing	8

1	IJ	Ø	***	40 av av
2	23 Ap	proved For Rele	ease 20 <b>04/</b> 10/28 :	CIA-RDP80-04794R000100230003-3
3	31	Ø	100%	***
4	3.	3	Ø%	(3) Reason I
5	Ø	Ø		(5) Reason 1
Software	Modification	•		READ VERIFY INSTALLED
6	.3	3	ø%	(2) Reason II (1) Reason I
7	1Ø	3	77%	(3) Reason I
8	41	1Ø	80%	(4) Reason I
Narduara	Modification		4	(6) Reason II
naidware		•	0.07	DATA CHANNEL ADJUSTED
9	15	2	88%	(2) Reason I
10	Ø	Ø		***
11	23	Ø	100%	•••
12	Ø	Ø		•••
13	2Ø	1	· 95%	(1) Reason IV
14	21	1	95%	
15	Ø	Ø		***
16	18	2	89%	(2) Reason III
<b>17-</b> 2Ø	21	Ø	100%	(a) Medoyn III
12 13 14 15 16	Ø 2Ø 21 Ø 18	Ø 1 1 Ø 2	95% 95%  89%	(1) Reason IV (1) Reason I  (2) Reason III

#### ASCEND SUMMARY

SSION	# ASCENDS	# FAILURES	% SUCCESSFUL	COMMENTS
1-2	. Ø	Ø		•••
3	20	1	95%	(1) Reason II or V
Ĺ	6	2	67%	(2) Reason II or V
5	Ø	Ø		
Software	Modification	n ·		READ VERIFY INSTALLED
6-7	· Ø	Ø		·
8	23	7	77%	(1) Reason VII
				(5) Reason V
				(1) Reason VI
Hardwar	e Medificatio	n		DATA CHANNEL ADJUSTED
9-20	77	Ø	100%	No file loss after Read Verify in- stalled and Data Channel alignment modification made.

#### REASONS

- -Bad tracks existed at two locations on BSSØØ1. Handling of these tracks is a recovery function, not planned for PSAT.

  Specific tracks were: Cylinder 28, Track 8 & Cylinder 288,

  Track 5.

  -Data Channel Read electronics improperly set-up to handle drop-
- (11) Reason II -Data Channel Read electronics improperly set-up to handle dropouts. Found prototype unit requires separate set-up procedure. Adjusted R11 on Assembly 6211540 to eliminate errors.
- (2) Reason III -Overflow record which spanned cylinder boundary. Error recovery function not planned for PSAT.
- (1) Reason IV -Demarkable block found. Recovered on retry at different tape location. Automatic demark not PSAT function.
- (7) Reason V -Read Verify function required as part of each Descend operation.

  Installed for usage after Session #5.
- (1) Reason VI Data Channel wire found disconnected after PSAT at Pin 22, J2, of Assembly 621139. This file was recoverable after reconnecting this wire.
- (1) Reason VII -Reserve failure. Recovery not supported for PSAT.
  Approved For Release 2004/10/28: CIA-RDP80-01794R000100230003-3

#### OTHER HARDWARE FAILURES

DA11-B

Two failures attributed to malfunction of this device. Replaced first portion after Session #1, remainder after Session #4.

SA11/TDIF Interrupt Handling Eight (8) failures attributed to inability of SA11 and TDIF hardware to properly handle simultaneous interrupts. Missing wire added to SA11. TDIF design modified. Solution implemented and fully tested.

#### PSAT ASCEND & DESCEND SUIDINRY

	DESCEND	ASCEND
Sessions 1-20:	•	
Attempted	231	126
Completed	2Ø5	116
Failed	26	10
Success Ratio	89%	92%
Séssions 9-20:		
Attempted	118	<b>77</b>
Completed	112	77
Failed	6	Ø
Success Ratio	95%	. 100%

#### CONCLUSIONS:

- No file loss on Ascend after Read Verify and Data Channel change implemented.
- All Descend failures are attributable to recovery functions not supported for PSAT.

#### ABILITY TO PROCESS FILES

#### MSS Design Specification

Provides, in Figure 12, detailed analysis of representative MSS activity.

Ampex considers this a performance specification against which the final System can be tested.

#### SYSTEM AVAILABILITY

#### MSS Design Specification

Section 11.5 guarantees System up-time in excess of 95%.

#### • DATA RELLABILITY

#### ORACLE MSS System

Proposal defines dependencies in Section 12.2 of accuracy on media reliability. This translates into the following set of requirements:

#### WRITE (DESCEND)

- Qualified Tape Only
- Read Verify
- Automatic Demark

#### READ (ASCEND)

- Reread
- Extended Recovery Procedures

NOTE: All data reliability figures assume the above procedures have been followed. In any test where data reliability is to be measured, the test size must be at least 10 x the lowest common denominator in the rate. To measure rate of 1 error/2.5 x 10 bytes, at least 2.5 x 10 bytes should be read during that period.

## TMS1 "TABLON" SYSTEM PERFORMANCE

REF. PROPOSAL 9-2

926 Hours

## LEVEL A/B PERFORMANCE SUMMARY

Level A 3/22-4/29/72 (326 Hours)

Calendar:

Level B 10/3	1/12/8/72 (600 Hour	s)	
		CDCCXCI CATYON	MARGIN
Activity:	ACTUAL	<u>SPECIFICATION</u>	PAROTA
Bits Mritten: Multi-Blk Single-Blk Total	$0.39 \times 10^{12}_{12}$ $0.41 \times 10^{12}$ $0.80 \times 10^{12}$	•	
Bits Read: Multi-Blk Single-Blk Total	$\begin{array}{c} 2.89 \times 10^{12} \\ 1.92 \times 10^{12} \\ 4.81 \times 10^{12} \end{array}$	•	•
R/W Total	5.61 x 10 <sup>12</sup>	$0.77 \times 10^{12}$	7.3
. Bulk Updates-in-Place	e 55121 ·		
Reread Rate (for error recovery)	0.4/1000 Blks	4.0/1000 Blks	10.0
*Unrecoverable Error Ra	te 1.5 x 10 <sup>-11</sup>	5 x 10 <sup>-11</sup>	3.3
Block Demark Rate: Tape Pretest After Pretest	0.009% 0.0045%	1%	111 222
Tape Life (Reads to Block Failure)	3020	1200	2.5

#### INTERPRETATION OF SPECIFIED ERROR RATES

• UNRECOVERABLE ERROR RATE

RATE = 5 X 
$$10^{-11} = \frac{1}{2 \times 10^{10}} = \frac{1}{8 \times 2.5 \times 10^9}$$

HARD ERRORS/DAY

RATE 
$$\approx$$
 (ERROR RATE) (TOTAL DATA TRANSFERRED PER DAY)  
= (1/2.5 x 10<sup>9</sup>) (5.2 x 10<sup>9</sup>)  $\approx$  2

<sup>(1)</sup> RFP, Page 8 f).

<sup>(2)</sup> Table 12, MSS Design Spec.

#### SUMMARY OF SOFTWARE ERRORS

Session	n # <b>'</b> s '	Occurrences	Description	Fix Implemented
2.		2	<ul> <li>Error messages &amp; completion messages not printed on flush command.</li> </ul>	Fixed during PSAT
4	:	1	"Setup complete" message in error should have been "breakdown complete". Interpreter cancelled job.	Fixed during PSAT
4		1	Segment time limit currently at 10 instead of 1. File transfer segmentation limit currently at 17 segments for descenddisallowing large files.	Final release (Rl limited)
4		.1	SRQ full - request queue filled with job stream \$1803MBL - set up for Biggie 1,2,3, &. 4. Messages prioritized during PSAT to drop low priority information only when full. Final system will have sufficient space.	Partial fix during PSAT
7		. 1	◆ Flush failure - nothing happened. Software timeout to TDP after lost interrupt. Error recovery will correct this.	Final release
. 9		1	MSS aborted - incorrect MFD entries due to manual restart procedures. Error recovery will correct this.	Final release
10		1	◆ MSS sent incorrect message to host then hung looping. Manual restart procedure and incorrect MFD entries. Error recovery will correct this.	Final release

# Key: • Hard failure - caused system abort or required IPL to continue

- Incorrect operation system did not function to specification
- Interpretation Approved to kelease 2004 10 28: CASTUP 80-01794 8000100230003-3

Session #'s	Occurrences	Description	Fix Implemented
13	1	• File conflicts. WM logic erroneously treated DISP on file required for 3 steps of a job.	Fixed during PSAT
13,16	3	<ul> <li>Priority conflicts - LIFO instead of FIFO within priority.</li> </ul>	Fixed after PSAT
13	1	<ul> <li>Non-recognition of change in BSS config- uration unless MSGØ91 received at IPL time.</li> </ul>	Fixed after PSAT
17,18,19	3	<ul> <li>Deallocation did not stop - min/max logic not functioning correctly.</li> </ul>	Fixed after PSAT
17	<b>1</b>	Allocation lockout, space de-allocated on disk without MSS notification, wait loop for space. Error recovery will handle this.	Final release
20	1	• Display file abort - allocation lockout, op command had conflicting information on aborted. Error recovery will handle this.	Final release
	18		

Key:

- ♦ Hard failure caused system abort or required IPL to continue (6)
- Incorrect operation system did not function to specification (9)
- Interpretation of operation no files lost, jobs ran ok (3)

12-16-75

#### TMS-2 MASS STORAGE SYSTEM

#### ACTION ITEM 1 - OCTOBER REVIEW

#### o ISSUE:

CONCURRENT ACCESS TO INDIVIDUAL TRANSPORT DRIVERS FROM BOTH STORAGE CONTROL PROCESSORS.

o AMPEX POSITION:

Not required by Contract or Specification.

#### o RATIONALE:

- 1. TRANSPORT DRIVER INTERFACE (TDIF) DESIGN ENABLES ONLY ONE TDIF TO BE IN CONTROL OF THE SCP/TD INTERCONNECT BUSS AT ANY GIVEN TIME.
- 2. MSS Design/Specification cable diagram on page 172 INDICATES SINGLE CABLE.
- 3. ARCHITECTURE CONFIRMED VIA "ORACLE MAINTENANCE AND DIAGNOSTICS" ON PAGE 150, PARAGRAPH 2.

### ACTION ITEM 2 - OCTOBER REVIEW

o ISSUE:

MAXIMUM HARDWARE CONFIGURATION OF 6 TD's, 64 TAPE TRANSPORTS, 3 DC's, AND 6 EDCP's does not have "perfect switching" CAPABILITY.

o AMPEX POSITION:

WILL PROVIDE "PERFECT SWITCHING" CAPABILITY WHEN AGENCY ORDERS MAXIMUM HARDWARE CONFIGURATION.

MS 12-15-75

# ACTION ITEM 3 - OCTOBER REVIEW

#### o ISSUE:

A Storage Control Processor requires a dedicated disk controller to access the Mass Storage System's private files.

#### o AMPEX POSITION:

THE TMS-2 MSS CAN OPERATE WITH A SHARED BSS/MSS CONTROLLER.

AMPEX RECOMMENDS A DEDICATED DISK CONTROLLER FOR PERFORMANCE

CONSIDERATIONS.

#### o RATIONALE:

- 1. Dedicated disk and controller included in original proposal page 4-5 and in IISS Design/Spec page 7-8.
- 2. SYSTEM ARCHITECTURE IS SUCH THAT IN A TWO(2) CONTROLLER SYSTEM AS PROPOSED BY THE AGENCY WHEN BOTH EDCP'S ARE CONNECTED AND STAGING FILES, SCP CANNOT ACCESS PRIVATE DISKS FOR FILE REQUEST PROCESSING.

WIIS

**12-**15-75

# Approved For Release 2004/10/28 : CIA-RDP80-01794R000100230003-3 INS-2 MASS STORAGE SYSTEM

#### ACTION ITEM 4 - OCTOBER REVIEW

#### o ISSUE:

Functions are not split and/or shared between the two(2) Storage Control Processors.

#### o AMPEX POSITION:

- 1. High confidence that software resident in a single SCP WILL MEET SYSTEM PERFORMANCE NEEDS.
- 2. PRIMARY REASON FOR SECOND SCP IS SYSTEM REDUNDANCY.
  - 3. AMPEX ERRED, SHOULD HAVE ADVISED AGENCY SOONER.

#### o RATIONALE:

- 1. SCP NOT LIMITING ELEMENT IN SYSTEM PERFORMANCE.
- 2. AMPEX "COST-TO-COMPLETE" ESTIMATE USED TO NEGOTIATE CEILING PRICE ASSUMED SINGLE SCP APPROACH.

WMS

**12-1**5-75

### -Approved For Releast 20048 0 28 A € A - R × P 7 1794R000100230003-3

#### S/W SYSTEM FOR SINGLE SCP

o 1975 Software Development Based On This Concept.

#### o Performance

Spec'd Performance Can Be Met Or Exceeded With This Concept.

Both For Present and Expanded Configuration. Ampex Confidence -- Very High!!

Performance Limits:

1 DSS (SEARCHES)

2 PRIVATE DISK (SEEKS)

3 SCP CORE MEMORY

4 SCP CYCLES

ALSO, HOST OVERHEAD, ETC.

#### O ADVANTAGES

- Overall System More Reliable (Less Active Hardware)
- MTTR IMPROVED (A/B TESTS, SPARES CONSIDERATIONS)
- In Case Of Computer Failure: No Degradation
- "WATCH DOG" PROGRAM IN SECOND CPU SUPPLIED
- SECOND CPU CAN BE BACKUP FOR EDCP (PURCHASE TDIF)
- THIS TYPE SYSTEM WILL BE SUPPORTED FOR GENERAL MARKET

## COMPLETION PLANNING

- RWC PSAT Confidence Test
   One(1) Day Mid-January 1976
- o Internal Software Design Implementation Review 12-30 January 1976
- FINAL RELEASE SOFTWARE SCHEDULE
  - UPDATED MANPOWER PLAN
  - UPDATED FUNCTIONS LIST
  - AGENCY REVIEW MID-FEBRUARY 1976
- O SUNNYVALE PSAT PLANNING
  - AGENCY TEST DEFINITION, ACCEPTANCE CRITERIA, PROCEDURE MID-FEBRUARY 1976.
  - AMPEX INTERNAL TEST MINIMUM THIRTY (30) DAYS.
  - AGENCY TEST TARGET SCHEDULE MAY 1976.